

Pressure Measurement Transmitters with WirelessHART

SITRANS P280 for gauge and absolute pressure

Overview



SITRANS P280 for flexible and cost-effective applications in pressure monitoring

- Supports the WirelessHART standard (HART V 7.1)
- Very high security level for wireless data transmission
- Built-in local user interface (LUI) with 3-button operation
- Optimum display and readability using graphical display (104 x 80 pixels) with integrated backlight
- Stand-by (deep sleep phase) can be activated and deactivated device with push of a button
- Battery power supply
- Battery service life up to 5 years
- Extend battery service life with HART modem interface which can be shut off
- Optimized power consumption through new design, and increase in battery service life.
- Simple configuration thanks to SIMATIC PDM
- Device meets IP65 degree of protection
- Can be used for absolute and gauge pressure measurements

Benefits

The SITRANS P280 is a pressure transmitter that features Wireless HART as the standard communication interface.

Also available is a wired interface to connect a HART modem:

- Flexible pressure measurements
- Save costs on wiring for difficult installation conditions. Wireless technology offers cost advantages in cases where extensive wiring cost would normally apply.
- It enables additional hitherto unfeasible measuring points, particularly for monitoring purposes.
- Easy installation on moveable equipment
- Enables cost-effective temporary measurements, for example for process optimizations.
- Optimum solution in addition to wired communication and new possibilities for system solutions in process automation

Application

The SITRANS P280 is a WirelessHART field device for measuring absolute and gauge pressure.

The measuring ranges for absolute and gauge pressure measurements are 0 to 2, 10, 50, 200 and 400 bar (0 to 29, 145, 725, 2900 and 5800 psi).

The sensor is integrated into the transmitter housing.

On the wireless communication side, the transmitter supports the WirelessHART standard. A HART modem can be connected to the transmitter particularly for initial commissioning, alternatively the device can be commissioned comfortably by means of the local pushbuttons w/o any additional handset devices.

It can be used in all industries and applications in non-explosive areas.

Design

The SITRANS P280 has a robust aluminum enclosure and is suitable for outside use. It conforms with the IP65 safety class.

The operating temperature range is -40 to +80 °C (-40 to +176 °F). Power supply is provided through an integrated battery, which is available as an accessory. The device is only approved for operation with this battery.

The aerial features a rotatable joint which can be used for directional alignment. Wireless signals can thus be optimally received and transmitted.

A special highlight is the option for direct operation on the device. The operating strategy used in this case seamlessly integrates into the strategy of all new Siemens field devices.

Using the device's control buttons, it is easy to turn the HART modem interface of the device on and off. The device can be put to passive status and reactivated at any time. This helps to extend the service life of the battery.

The SITRANS P280 transmitter features a ceramic measuring cell for gauge and absolute pressure measurements.

Function

The SITRANS P280 can join to a WirelessHART network. It can be parameterized and operated through this network. Measured process values are transported via the network to the SIEMENS IE/WSN-PA link.

Field device data received by the IE/WSN-PA LINK is transmitted to the connected systems, for example the process control system SIMATIC PCS 7. For an introduction of WirelessHART, please see the FI 01 catalogue, section 9 or <http://www.siemens.com/wirelesshart>.

Detailed information on IE/WSN-PA can be found in the FI 01 catalogue, section 9 or <http://www.siemens.com/wirelesshart>.

Pressure Measurement Transmitters with WirelessHART


SITRANS P280 for gauge and absolute pressure

Integration

Connecting to SIMATIC PCS 7

The integration of field devices in SIMATIC PCS 7 and other process control systems can now be done seamlessly and cost-effectively with wireless technology, especially in situations where high wiring costs may be expected. Of particular interest are measuring points which are to be added and for which no MSR wiring is available.

Where larger distances between the IW/WSN-PA LINK and control systems need to be overcome, this connection can also be implemented on a wireless and cost-effective basis using the products of the SCALANCE W family.



Integration of a meshed network in SIMATIC PCS 7

Configuration

Configuration of the SITRANS P280 may be carried out as follows:

- Initial commissioning for the SITRANS P280 with SIMATIC PDM is generally carried out via a HART modem or the integrated local user interface, since the network ID and join key must be set up on the device before it can be accepted and integrated into the WirelessHART network.
- Once it is integrated into the network, the device can be conveniently operated with the WirelessHART network, the onsite HART modem or via the local user interface.
- Siemens WirelessHART devices operate with optimum coexistence to SCALANCE W family products.

Technical specifications

SITRANS P280 WirelessHART pressure transmitter

Mode of operation	
Measuring principle	piezo-resistive
Measured variable	Gauge and absolute pressure
Gauge pressure input	
Measuring range	Overload limit/Bursting pressure
0 ... 2 bar (0 ... 29 psi)	5 bar (72.5 psi)
0 ... 10 bar (0 ... 145 psi)	50 bar (363 psi)
0 ... 50 bar (0 ... 725 psi)	250 bar (1740 psi)
0 ... 200 bar (0 ... 2900 psi)	650 bar (7250 psi)
0 ... 400 bar (0 ... 5800 psi)	650 bar (7250 psi)
Units	mbar, bar, mmH ₂ O, inH ₂ O, atm, Torr, gcm ² , kgcm ² , mPa, KPa, Pa, psi, mmHG, mmH ₂ O, ftH ₂ O, inHG, inH ₂ O
Absolute pressure input	
Measuring range	Overload limit/Bursting pressure
0 ... 2 bar a (0 ... 29 psia)	5 bar a (72.5 psia)
0 ... 10 bar a (0 ... 145 psia)	50 bar a (363 psia)
0 ... 50 bar a (0 ... 725 psia)	250 bar a (1740 psia)
0 ... 200 bar a (0 ... 2900 psia)	650 bar a (7250 psia)
0 ... 400 bar a (0 ... 5800 psia)	650 bar a (7250 psia)
Units	mbar, bar, mmH ₂ O, inH ₂ O, atm, Torr, gcm ² , kgcm ² , mPa, KPa, Pa, psi, mmHG, mmH ₂ O, ftH ₂ O, inHG, inH ₂ O
Output	
Output signal	2.4 GHz Wireless signal with TSMP (Time Synchronized Mesh Protocol)
Measuring accuracy	
Error in measurement at limit setting incl. hysteresis and reproducibility	typ. 0.17 % of sensor's span max. 0.25 % of sensor's span
Long-term stability	max. ± 0.25 % of sensor/year span
Influence of ambient temperature	typ. 0.07 %/10K, max. 0.2 %/10 K of sensor's span
Rated conditions	
Ambient conditions	
• Ambient temperature	-40 ... +80 °C (-40 ... +176 °F) (in ambient temperatures below -20 °C (-4 °F) and above +70 °C (158 °F), readability of the display is limited.)
• Storage temperature	-40 ... +85 °C (-40 ... +185 °F)
• Relative humidity	< 95 %
Climatic class	4K4H in accordance with EN 60721-3-4 (stationary use at locations not protected against weather)
Degree of protection	IP65/NEMA 4
Allowable media temperature	-40 ... 85 °C (-40 ... +185 °F)

Pressure Measurement

Transmitters with WirelessHART

SITRANS P280 for gauge and absolute pressure

Design

Enclosure material	low-copper die-cast aluminum, GD-AISi12
Shock resistance	in accordance with DIN EN 60068-2-29 / 03.95
Resistance to vibration	in accordance with DIN EN 60068-2-6/ 12.07 20 ≤ f ≤ 2000 Hz 0.01 g ² /Hz
Weight	
• without battery	1.5 kg (3.31 lb)
• With battery	1.6 kg (3.53 lb)
Dimensions (W x H x D)	See Dimensional drawing
Process connection	<ul style="list-style-type: none"> G½B male thread as per EN837-1 ½-14 NPT
Sensor break	Is recognized

Displays and controls

Display (with illumination)	
• Size of display	104 x 80 pixels
• Number of digits	adjustable
• Number of spaces after comma	adjustable
Setting options	<ul style="list-style-type: none"> on site with 3 buttons with SIMATIC PDM or HART-Communicator

Power supply

Battery	3.6 V DC
---------	----------

Communication

Radio	WirelessHART V7.1 conforming
Transmission frequency band	2.4 GHz (ISM-Band)
Transmission range under reference conditions	Up to 250 m (line of sight) in outside areas Up to 50 m (greatly dependent on obstacles) in inside areas
Communication interfaces	<ul style="list-style-type: none"> HART communication with HART modem WirelessHART

Certificates and approvals

Wireless communication approvals	R&TTE FCC
Classification according to pressure equipment directive (PED 97/23/EC)	Gases: Fluid group 1 Liquids: Fluid group 1; meets requirements as per Section 3, Subsection 3 (sound engineering practice)

Selection and Ordering data

SITRANS P280 WirelessHART pressure transmitter

Order No.

D) ▶ 7MP1120-

(Required battery not included with delivery, see accessories)

Measuring cell filling

Dry measuring cell

Measuring span

Gauge pressure

0 ... 2 bar (0 ... 29 psi)
0 ... 10 bar (0 ... 145 psi)
0 ... 50 bar (0 ... 725 psi)
0 ... 200 bar (0 ... 2900 psi)
0 ... 400 bar (0 ... 5800 psi)

Absolute pressure

0 ... 2 bar a (0 ... 29 psia)
0 ... 10 bar a (0 ... 145 psia)
0 ... 50 bar a (0 ... 725 psia)
0 ... 200 bar a (0 ... 2900 psia)
0 ... 400 bar a (0 ... 5800 psia)

Wetted parts

Ceramic

Display

Display, visible

Enclosure

Die-cast aluminum

Process connection

G½ as per EN 837-1
½-14 NPT

Explosion protection

Without

Antenna

Variable, attached to device

Further designs

Please add "-Z" to Order No. and specify Order code(s) and plain text.

Stainless steel tag plate (measuring point description)

max. 16 digits entered in plain text
Y15:

Measuring point message
max. 27 characters entered in plain text: Y16:
.....


Accessories

Lithium battery for SITRANS TF280/P280	D) ▶	7MP1990-0AA00
Mounting bracket, steel		7MF4997-1AC
Mounting bracket, stainless steel	▶	7MF4997-1AJ
Cover, die-cast aluminum, without window	F)	7MF4997-1BB
Cover, die-cast aluminum, with window	F) ▶	7MF4997-1BE
IE/WSN-PA LINK		see Sec. 8
HART modem with RS232 interface	D) ▶	7MF4997-1DA
HART modem with USB interface	D) ▶	7MF4997-1DB
SIMATIC PDM		see Sec. 9

▶ Available ex stock

D) Subject to export regulations AL: N, EAR 99H.

F) Subject to export regulations AL: 9I999, ECCN: N.



Order code

Y15


Y16

Order No.

Pressure Measurement Transmitters with WirelessHART

SITRANS P280
for gauge and absolute pressure

Dimensional drawings




SITRANS P280 WirelessHART pressure transmitter, process connection G $\frac{1}{2}$ " , dimensions in mm (inch)
The dimensional drawing of the mounting bracket see on page 2/158.

Pressure Measurement

Transmitters with WirelessHART

SITRANS P280
for gauge and absolute pressure

2



SITRANS P280 WirelessHART pressure transmitter, process connection 1/2 - 14 NPT, dimensions in mm (inch)
The dimensional drawing of the mounting bracket see on page 2/158.